

Annexure D

BUILDING SAFETY CERTIFICATE

No.

Dated: 09/07/2025

It is certified that the existing building Sri Sai Vidyaniketan Residential School (name of the building or premises) at Diggi Sangameshwara Temple Road

..... (address) is having block(s)/Floor(s) as per details below:

| Detail of Block(s) in school | Block (1) | Block (2) | Block (3) | Block (4) | Block (5) | Block (6) |
|------------------------------|--------------------------------|-----------|-----------|-----------|-----------|-----------|
| No. of Floor(s) in the Block | Ground 2 Floor = 3 floor | | | | | |

The building is owned/occupied by Sri Sai Vidyaniketan Residential School (name of the Institution) have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of Asst. EE, PWD (Name of Department/ Govt.) on 25/06/2025 (date of inspection) in the presence of S. B. Reddy (Manager) (name and addresses of the Manager/Secretary or his representative) and that the building/premises is fit for occupancy for running school with effect from 09/07/2025 for a period of 03 years years in accordance with rule and subject to compliance of the specific conditions as appended.

- 1.
- 2.
- 3.
- 4.

Issued on 09/07/2025 at SHAHAPUR by

* Strike out whichever is not applicable. In case of block is more than six use separate sheet for detail.

Signature with Seal: 

Name: ಶ್ರೀಮಯೇಗಿ ಇರಾಜ್ ಕೆ.ಎ-ವಿಭಾಗ

Designation: ಶಾಸನರ ಜಿ.ಯಾದಗಿರಿ

Name & Address of Department/ Office: _____



ಕರ್ನಾಟಕ ಸರ್ಕಾರ
(ಲೋಕೋಪಯೋಗಿ ಇಲಾಖೆ)

ಕಾರ್ಯಾಲಯ

ಸಹಾಯಕ ಕಾರ್ಯನಿರ್ವಾಹಕ ಅಭಿಯಂತರರು
ಲೋಕೋಪಯೋಗಿ ಇಲಾಖೆ, ಉಪ-ವಿಭಾಗ
ಶಹಾಪುರ.

ಸಂ.ಸಕಾನಿ/ಲೋಇ/ಉ.ವಿ.ಶ/ಡಿ.ಬಿ/2024-25/501

ದಿನಾಂಕ: 18-01-2025

ಗೆ,

Principle

Sri, Sai Vidyaniketan Residential School
(Aff. No. 830815 & New School Code: 45724)
Diggi Road Shahapur-585223.

ಮಾನ್ಯರೆ,

ವಿಷಯ: ಭದ್ರತಾ ಪ್ರಮಾಣ ಪತ್ರ ಕೊಡುವ ಕುರಿತು.

ಉಲ್ಲೇಖ: ತಮ್ಮ ಪತ್ರ ದಿನಾಂಕ: 13/01/2025.

ಮೇಲಿನ ವಿಷಯಕ್ಕೆ ಸಂಬಂಧಿಸಿದಂತೆ, ಉಲ್ಲೇಖಿತ ಪತ್ರದನ್ವಯ Sri, Sai Vidyaniketan Residential School, Diggi Road Shahapur ಕಟ್ಟಡಕ್ಕೆ ಈ ಉಪ-ವಿಭಾಗದ ಶಾಖಾಧಿಕಾರಿಗಳು, ದಿನಾಂಕ: 17/01/2025 ರಂದು ಪರಿಶೀಲಿಸಿದಾಗ ಕಟ್ಟಡದ ಗೋಡೆ ಮತ್ತು ಮೇಲ್ಭಾಗವು ಸುರಕ್ಷಿತವಾಗಿದೆ ಎಂದು ಶಾಖಾಧಿಕಾರಿಗಳು ಪರಿಶೀಲಿಸಿ ವರದಿ ನೀಡಿರುತ್ತಾರೆ. ಆದ್ದರಿಂದ ಸದರಿ ವರದಿಯಂತೆ ಈ ಭದ್ರತಾ ಪ್ರಮಾಣ ಪತ್ರವನ್ನು ನೀಡಲಾಗಿದೆ.

ತಮ್ಮ ವಿಶ್ವಾಸಿ,

ಸಹಾಯಕ ಕಾರ್ಯನಿರ್ವಾಹಕ ಅಭಿಯಂತರರು
ಲೋಕೋಪಯೋಗಿ ಇಲಾಖೆ, ಉಪ-ವಿಭಾಗ
ಶಹಾಪುರ.